

LCID

State of North Carolina
Department of Environment and Natural Resources
Division of Waste Management


LAND CLEARING & INERT DEBRIS
LANDFILL
Facility Annual Report
For the period of July 1, 2011-June 30, 2012

According to (G.S. 130A-309.09D(b)) completed forms must be returned by August 1, 2012 and a copy of this report must be sent to the County Manager of each county from which waste was received. If you have questions or require assistance in completing this report, contact your Regional Environmental Senior Specialist.

Facility Name: Piney Hill Acres LCID

Permit: 34AA-LCID- ID: P0533

Facility Website (URL):



Physical Address		Mailing Address	
Street 1: 2020 Piney Grove Rd		Street 1: 2020 Piney Hill Acres	
Street 2:		Street 2:	
City: Kernersville	County: Forsyth	City: Kernersville	
State: North Carolina	Zip: 27284	State: North Carolina Zip: 27284	
Primary Facility Contact Person		Billing Contact Person	
Name: David Lee Lawson		Name: David Lee Lawson	
Phone: (336) 682-2317	Fax:	Phone: (336) 682-2317	Fax:
Email: dlawson76@triad.rr.com		Email: dlawson76@triad.rr.com	

1. Tipping Fee: \$35.00 per Single Axle (10' Box) 8 Cu. Yds.
 Tipping Fee: \$45.00 per Tandem Axle (16' Box) 17 Cu. Yds.
 Tipping Fee: \$75.00 per Dump Trailer (28' Box) 30 Cu. Yds.

2. Estimate the amount of waste taken in an average week at this facility? 235 ☐ tons ☒ cubic yards

3. How many weeks did you operate this year? 52

4. What are the hours/days of operation for this facility? Mon-Fri 7:30am - 5:00pm Sat 7:30 - 1:00pm

5. What is the acreage of the footprint of the waste on site as of June 30? 1.95 +/- Acre(s)

6. Did your facility stop receiving waste during this past Fiscal Year? ☐ Yes ☒ No

If so, please report the date this occurred:

REMINDER: According to (G.S. 130A-309.09D(b)), this report must be sent to the Regional Environmental Senior Specialist for your area and a copy of this report must be sent to the County Manager of each county from which waste was received.

Please return your completed report to:

C.T. Gerstell
610 East Center Avenue
Mooresville, NC 28115
phone: 704.235.2144 email: Charles.Gerstall@ncdenr.gov

CERTIFICATION: I certify that the information provided is an accurate representation of the activity at this facility.

Signature:

David Lee Lawson

Date: July 6, 2012

Name: David Lee Lawson

Title: Owner/ Operator

Phone Number: (336) 682-2317

Email: dlawson76@triad.rr.com

Facility Name: Piney Hill Acres LCID Permit: 34AA-LCID-

Address: 2020 Piney Grove Rd

City: Kernersville State: North Carolina Zip: 27284

Person completing Assessment: Rebecca Lawson Date: _____

Phone Number: (336) 399-8247 Fax: _____ Email: notjustpansies@ymail.com

Instructions: Please indicate either *Yes* or *No* for each Receptor and Post Closure Maintenance question. Then please determine the distance or distances for each Receptor from the *Edge of Waste* (using range finders and/or GIS maps) and type that information into the form. Please attach additional information including GIS maps, lists of potable well locations, etc.

Receptors

1. Are there Residential Dwellings Within 1,500 feet of the Edge of Waste? ☒ Yes ☐ No
If Yes, how many? 5
What are the three closest distances from the *Edge of Waste*? 222 Feet 246 Feet 249 Feet
2. Are there Potable Wells Within 1,500 feet of the Edge of Waste? ☒ Yes ☐ No
If Yes, how many? 5
What are the three closest distances from the *Edge of Waste*? 222 Feet 246 Feet 249 Feet
3. Are there Community/Municipal Wells Within 1,500 feet of the Edge of Waste? ☐ Yes ☒ No
If Yes, how many? _____
What are the three closest distances from the *Edge of Waste*? _____ Feet _____ Feet _____ Feet
4. Are there Surface Water Bodies Within 1,500 feet of the Edge of Waste? ☐ Yes ☒ No
If Yes, how many? _____
What are the three closest distances from the *Edge of Waste*? _____ Feet _____ Feet _____ Feet
Please list the names of the water bodies: _____
5. Is Public Water Available Within 1,500 feet of the Edge of Waste? ☒ Yes ☐ No
If Yes, how many of the Residential Dwellings noted above are connected? 4

Corrective Measures

6. Is there an active methane extraction system (blower, flare, etc.)? ☐ Yes ☒ No
 7. Is there a passive methane extraction system (trench, vents in cap, flare, etc.)? ☐ Yes ☒ No
 8. Is there groundwater remediation taking place on site? ☐ Yes ☒ No
- If Yes, what is the specific remedial technology used? _____

Comments

Four out of the five residential dwellings are using public water. The four wells not being used for potable water have not been filled in.